

BUILDING SAFETY CERTIFICATE

LETTER No.352

Dated: 23.04.2025

It is certified that the existing building Satguru Public School Vill. Kalalwla, Bathinda (name of the building or premises) at Vill. Kalalwla Bathinda (address) is having block(s)/ Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	GF ONE	XXX	XXX	XXX	XXX	XXX

The building is owned/ occupied by Satguru Public School Vill. Kalalwla, Bathinda (name of the Institution) have complied with the Building safety requirements for normal use as School building and verified by the officers concerned of PWD (B&R) BATHINDA (Name of Department/ Govt.) on 22.04.2025 (date of inspection) in the presence of Smt. Madhu Bansal Headmistress (name & addresses of the Manager/ Secretary or his representative) and that the building/ premises is fit for occupancy for running school with effect from: 23.04.2025 for a period of One years in accordance with rule and subject to compliance of the specific conditions as appended.

1. There should be a plan to rescue the student in case of fire or emergency circumstances.
2. This department must be immediately informed about the addition/ alteration in the building or any damage to the building due to natural calamity and it would be the responsibility of school management to maintain and repair the building.
3. This building has not been constructed by this department. As per Structure Safety Certificate issued by M/s Next Architects, Bathinda vide its letter No. SC/101 Dated: 15.04.2025 this building is safe for use of school for the year 2025-26.
4. Building inspection has been received as per the Govt. Instruction issued from time to time.

This certificate is not valid for legal purpose.

Issued on 23.04.2025 at Bathinda by

Signature with Seal

Name:

Designation:

Name & Address of Department/
Office

Executive Engineer
Division. No. 2 PWD, B&R Br.
Bathinda